



UI Bulletin #179c

Subject: **NEW** Wide Body Sideview Mirrors

Models Affected: Silverado MD Trucks (4500,5500,6500)
Models Years Affected: 2019 - beyond
Origination Date: April 16, 2021
Revision Date: August 30, 2021

ADVISORY:

Condition/Concern:

Some Customers and/or upfitters have expressed concerns with regards to the limited rearward visibility from the standard factory camper style mirrors when the vehicle is outfitted with a service body of an 80" or greater width.

Repair/Recommendation:

The following 2 new options are now available for ordering...

- **DGD – Mirrors, outside, black with manual folding, manual adjusting, high visibility vertical camper style, and lower convex spotter glass, 102", Wide Load**
- **DGP – Mirrors, outside, black, heated and power adjustable, high visibility vertical camper style, and lower convex spotter glass, manual folding. Convex glass is not heated or power adjustable. 102", Wide load.**

These new wide body mirrors can be retrofitted for improved visibility on the 2019 and beyond model year MD Silverado trucks not built with them. Follow GM published Service Information replacement procedures replacing the factory install standard camper style mirrors (DF2 (manual) and DPN (power)) using the links below...

[Outside Rearview Mirror Replacement \(DF2\)](#)

[Outside Rearview Mirror Replacement \(DPN\)](#)

Additional Information:

The following are the service replacement part numbers for the new wide body mirrors

- o 84875328 - O/S RR View Manual (Black) LH Mirror (102") (DGD)
- o 85140644 - O/S RR View Manual (Black) RH Mirror (102") – (DGD)
- o 85143262 - O/S RR View - Power (Black) RH Mirror (102") (DGP)
- o 85143266 - O/S RR View - Power (Black) LH Mirror (102") (DGP)

General Motors Upfitter Integration

<http://www.gmupfitter.com>